

Inspection Photos
Location Name: Hungenberg 29-21
Location ID: 4302849



Photo 1 – Pumping Unit – Weeds



Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Hungenberg 29-21
Location ID: 4302849



Photo 3 – Wellhead



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Hungenberg 29-21
Location ID: 4302849



Photo 5 – Stained Soil at Wellhead