

Inspection Photos
Location Name: Stromquist 34-21
Location ID: 336262



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Stromquist 34-21
Location ID: 336262



Photo 3 TB sign



Photo 4 TB

Inspection Photos
Location Name: Stromquist 34-21
Location ID: 336262



Photo 5 vertical separator



Photo 6 ECD

Inspection Photos
Location Name: Stromquist 34-21
Location ID: 336262



Photo 7 Horizontal Heated Separators



Photo 8 Gas Meter Run

Location ID: 336262




Photo 9 Card in meter house indicates current calibration