



# Whiting Oil & Gas Corporation

## Razor 26 CPB Release Photo Documentation

Location ID: 435421

Sec 26 10N 58W

8/13/2021



Source Area  
Red arrow indicates failure point



View of initial clean up