

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32NENE

Location ID: 324119



Photo #4766 from entrance to location.



Photo #4767 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32NENE

Location ID: 324119



Photo #4768 Separator missing required information.



Photo #4768 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32NENE

Location ID: 324119



Photo #4770 Location lacks stabilization.



Photo #4771 Insufficient tracking controls at entrance to location.