

Inspection Photos

API: 071-08575

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/11/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021

Inspection Photos



Photo 1. Facing south toward the location. All equipment has been removed and the location was recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021

Inspection Photos



Photo 2. Facing south at the location. Most of the vegetation shown in this photo is a sterile cover crop which will not regenerate during the next growing season. There are perennial vegetation establishing underneath the cover crop.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021

Inspection Photos



Photo 3. View of growing cover shows the triticale cover crop and the red arrows point to some of the perennial vegetation establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021

Inspection Photos



Photo 4. Facing west at the south side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021

Inspection Photos



Photo 5. Facing northeast toward the location.



Inspection Photos



Photo 6. Facing toward the northwest side of the location. This area is not stabilized and additional reclamation will need to be performed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08575 | Date: 8/11/2021