

Caerus Piceance LLC
RH 1
Location # 323983



Location/lack of separator bath signage



location



Caerus Piceance LLC
RH 1
Location # 323983



Location/lack of battery signage



Lack of stabilization/compaction



Caerus Piceance LLC
RH 1
Location # 323983



Lack of stabilization/compaction



Lack of stabilization/compaction

