

Final Reclamation and Stormwater Inspection

August 12, 2021

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 426701

Inspection Document #: 697503152

Weld County, CO

Lot 3 Section 1 T7N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 1. Photo taken from the entrance of location, facing South. Photo illustrates unmanaged weeds throughout the entire location.



Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701




Photo 2. Photo taken from the northern access road, facing South. See comments under Photo 1.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 3. Photo taken from the northwestern location, facing South. See comments under Photo 1.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701




Photo 4. Photo taken from the northwestern location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 5. Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos
Location: Bridgman #1-1H
Location ID: 426701



Photo 6. Reference photo taken west of location, facing West.