

Inspection Photos
Operator: Simcoe
API: 067-07247
Date: 8/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing westward. Revegetation is progressing, largely with western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of the reference area comprised of ponderosa pine woodland with understory of gambel oak, Oregon grape, Junegrass, and squirreltail.