

Inspection Photos

8/13/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 449070

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 449070



Photo 1: Photos taken from the interim areas of the Location. Photo on left shows interim areas on the west end of the Location. Photo shows areas where uniform establishment is not occurring and inter-seeding is needed. Photo on right shows interim areas on the south end of the Location where uniform establishment is occurring.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 449070



Photo 2: Photo taken from the west end of the Location. Photo shows areas where uniform establishment is not occurring and inter-seeding is needed. Photo also shows BMPs to stabilize the slopes are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 449070



Photo 3: Photo shows sediment is filling ditch and culvert on the Location.