

Inspection Photos

API: 071-08776

Operator: XTO ENERGY INC

Inspection Date: 8/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 1. Facing southwest along the access road. The rock check dam has washed out and needs repair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 2. There is sediment accumulation along this rip/rap outlet which needs maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 3. Facing west along the access road. The rock check dam has washed out and needs repair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 4. Sediment has accumulated in this culvert along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 5. Facing northwest. Stormwater has eroded around the edge of this rock diversion. Additionally the road sides should be seeded to establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 6. Facing northwest along the road. Culverts are installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 7. Facing west near the location. There are noxious weeds in the area circled. It appears weed control was performed but the weeds are resprouting and will need additional control.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 8. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 9. There are noxious weeds in the area circled which are brown and wilted from weed control, however some of the weeds have dispersed seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021

Inspection Photos



Photo 10. Facing south along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08776 | Date: 8/16/2021