

# Inspection Photos

API: 071-09381

Operator: XTO ENERGY INC

Inspection Date: 8/16/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021

## Inspection Photos



**Photo 1.** Facing north toward the access road. The cattle guard is filled in with sediment and needs to be maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 2.** Stormwater is causing erosion down the access road which is filling in the cattleguard. Storm water needs to be diverted off the road to prevent erosion (berm, water bar). The cut slopes shown in upper right of the photo are not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 3.** Facing northwest toward the location. The perimeter straw bales have been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 4.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 5.** There was weed control performed at the location however some of the weeds have dispersed seed. Arrow points to Canada thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 6.** Facing southwest. The undesirable weeds (Russian thistle) were also wilted throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 7.** Facing northwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021



## Inspection Photos



**Photo 8.** Facing northeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 8/16/2021