

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912




Photo 1 weeds overgrown around WH sign

Photo 2 weeds overgrown around WH

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 3 weeds overgrown around pump jack parts

Photo 4 weeds overgrown around pump jack parts

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 5 weeds overgrown around pump jack parts

Photo 6 weeds overgrown through out location

Inspection Photos
Location Name: Leonard 24-21
Location ID: 318912



Photo 7 weeds overgrown around pump jack parts