

Inspection Photos
Location Name: Ditlev-Simonsen C1
Location ID: 318207



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Ditlev-Simonsen C1
Location ID: 318207



Photo 3 Weeds have been cut along access rd.

Photo 4 Weeds have been cut around location ROW, Pump Jack

Inspection Photos
Location Name: Ditlev-Simonsen C1
Location ID: 318207



**Photo 5 Weeds have been cut around location ROW,
Ancillary equipment.**

**Photo 6 Weeds have been cut around location ROW, trash
removed (old v belt)**

Inspection Photos
Location Name: Ditlev-Simonsen C1
Location ID: 318207



Photo 7 trash removed from pump jack base (old v belts)