

**Inspection Photos**  
**Location Name: Ditlev-Simonsen B1**  
**Location ID: 318206**



**Photo 1 WH sign**



**Photo 2 Stained soil has been removed from around WH**

**Inspection Photos**  
**Location Name: Ditlev-Simonsen B1**  
**Location ID: 318206**



**Photo 3 Weeds have been cut along access rd.**



**Photo 4 Pump Jack**

**Inspection Photos**  
**Location Name: Ditlev-Simonsen B1**  
**Location ID: 318206**



**Photo 5 Weeds have been cut around location ROW, trash  
picked up, Ancillary equipment.**