

Inspection Photos
Location Name: Lion Government 41-36
Location ID: 333231



Photo 1. Overview of location taken facing east. Annual weeds on location.



Photo 2. Sediment migration onto and across access road.



Inspection Photos
Location Name: Lion Government 41-36
Location ID: 333231



Photo 3. Sediment migration across access road.



Photo 4. Sediment migration off access road.

