

Inspection Photos
Location Name: Lasher 9
Location ID: 313178



Photo 1. Overview of location taken facing northwest.



Photo 2. Sediment migrating off location, down access road, off of access road.



Inspection Photos
Location Name: Lasher 9
Location ID: 313178



Photo 3. Sediment migrating onto location.



Photo 4. Sediment migrating onto location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lasher 9
Location ID: 313178



Photo 5. Sediment migrating onto location.



Photo 6. Sediment migrating onto location.



Inspection Photos
Location Name: Lasher 9
Location ID: 313178



Photo 7. Sediment migration off access road.



Photo 8. Stormwater BMPs overwhelmed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources