

Final Reclamation Inspection

August 17, 2021

Operator: BATES* JAMES EDWARD - 6575

API #: 05-001-06796

Inspection Document #: 697503157

Adams County, CO

SESE Section 7 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 1. Photo taken from the associated offsite tank battery, facing West. Photo illustrates the tank battery has been seeded and is reflective of reference area vegetative levels. Some kochia was observed but at less density than the reference area.



Photo 2. Reference photo taken east of the tank battery, facing East. See comments under Photo 1.

Inspection Photos
Location Name: WIERMAN #1
API #: 05-001-06796



Photo 3. Photo taken from the well location, facing East. Photo illustrates the well location is reflective of reference area vegetative levels.



Photo 4. Photo taken from the well location, facing North. See comments under Photo 3.