

TEP
GGU 3-29
Location # 323977



location



location

TEP
GGU 3-29
Location # 323977



Separator bath labeling



Separator bath labeling

TEP
GGU 3-29
Location # 323977



location



Debris

TEP
GGU 3-29
Location # 323977



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion