

**Inspection Photos**  
**Location Name: Lasher, W B 5**  
**Location ID: 312858**



**Photo 1. Overview of location taken at entrance facing north. Annual weeds on location.**



**Photo 2. Sediment migrating onto location.**



**Inspection Photos**  
**Location Name: Lasher, W B 5**  
**Location ID: 312858**



**Photo 3. Sediment migrating through ditch on location perimeter and then onto location. No BMPs observed in ditch.**



**Photo 4. Sediment migrating onto location from ditch in previous 2 photos.**





**Inspection Photos**  
**Location Name: Lasher, W B 5**  
**Location ID: 312858**



**Photo 5. Sediment migration onto location.**



**Photo 6. Sediment transported onto location. Close up of photo 5.**

