

Inspection Photos
Operator: Arkoma/Catamount
API: 067-05279
Date: 8/12/2021



Photo 1. View of the project area from the southern edge facing center. Observable vegetation is largely kochia weeds.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Visible vegetation is comprised of kochia.



Photo 3. View of kochia weeds (approx. 4 ft high) growing around submerged vessel.



Photo 4. View of straw wattles filled with sediment needing replacement and maintenance.



Photo 5. View of the reference area comprised pinyon and juniper woodland with understory of gambel oak, sagebrush, antelope bitterbrush, and squirreltail.