

Inspection Photos
Location Name: Federal 2-26
Location ID: 313020



Photo 1. Overview of location taken facing north. Annual weeds on location.



Photo 2. Signs not updated to current operator. Incomplete tank label. Animal burrows in berms.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal 2-26
Location ID: 313020



Photo 3. Sign not updated to current operator.




Photo 4. No bradenhead access apparent.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources