

Inspection Photos
Location Name: Wildfong 11-23
Location ID: 319086



Photo 1 – Wellhead Sign




Photo 2 – Wellhead – Unused Rods and Tubing



Inspection Photos
Location Name: Wildfong 11-23
Location ID: 319086



Photo 3 – ECD and Separator



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Wildfong 11-23
Location ID: 319086



Photo 5 – Tank



Photo 6 – Gas Meter



Inspection Photos
Location Name: Wildfong 11-23
Location ID: 319086




Photo 7 – Unmarked Risers