

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM /42-11 Frac Pad

Location ID: 334956



**Photo #4830 from entrance to location.**



**Photo #4831 Separators missing required information.**