## Phoenix Resources LLC, Mosher 1-1H 073-06393 Inspection #688311155

8/19/2021

**Routine Inspection** 



COLORADO


Oil & Gas Conservation Commission

Department of Natural Resources





Remove Well Shut In sign.




Well's LO/TO key.






Bradenhead is installed.



Gear box on pumping unit is leaking and on the ground.









Remove Facility Shut In sign.

Colorado Oil and Gas Conservation Commission 38.93772, -103.38835, 4819.6ft, 57° 08/19/2021 11:53:19 AM


400 BBL

AGT 2





Colorado Oil and Gas Conservation Commission 38.93794, -103.38806, 4796.6ft, 355 08/19/2021 11:54:36 AM



Check for pipe integrity.






May be bullet holes.

08/19/2021 11:54:56 AM














Injection pump, ~40 psi on next slide.

Colorado Oil and Gas Conservation Commission 38.93787, -103.38808, 4799.9ft, 148° 08/19/2021 11:53:57 AM



Flare.

Colorado Oil and Gas Conservation Commission 38.93825, -103.38802, 4790.0ft, 17° 08/19/2021 11:57:35 AM



## Remove unused equipment.