

**Inspection Photos**  
**Location Name: Muegge Hand 43-31**  
**Location ID: 319894**



**Photo #1 Tanks.**



**Photo #2 Separator.**

Inspection Photos  
Location Name: Muegge Hand 43-31  
Location ID: 319894



Photo #3 Meter.



Photo #4 Well Head



**Inspection Photos**  
**Location Name: Muegge Hand 43-31**  
**Location ID: 319894**



**Photo #5 Inadequate berms around tanks.**



**Photo #6 Stained soil.**