

Final Reclamation Inspection

August 17, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 319467

Inspection Document #: 701900044

Weld County, CO

SESE Section 7 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Carlson 1
Location ID: 319467



Photo 1. 2019 aerial imagery shows the well head and associated access road (north is up). Note: the tank battery is reclaimed and will be associated with location ID 330731.

Inspection Photos
Location Name: Carlson 1
Location ID: 319467




Photo 2. Overview photo of well head, access road and reference area taken from east end of well head using a drone. Photo shows corn crop within the well head and along access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Carlson 1
Location ID: 319467




Photo 3. Ground photo taken from eastern end of well head looking west up access road.

