

Final Reclamation Inspection

August 17, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323399

Inspection Document #: 701900046

Weld County, CO

NWSE Section 15 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Berg 33-5
Location ID: 323399




Photo 1. 2019 aerial imagery shows tank battery, well head and associated access road (north is up). Note: tank battery and well head shared same disturbance pad.

Inspection Photos
Location Name: Berg 33-5
Location ID: 323399




Photo 2. Overview photo of well head, tank battery, access road and reference area taken from north of well head using a drone. Photo shows crop within the well head and along access road appear consistent with adjacent reference area.

Inspection Photos
Location Name: Berg 33-5
Location ID: 323399




Photo 3. Ground photo taken northern end of well head and tank battery looking south.