

# Final Reclamation Inspection

August 17, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 336057

Inspection Document #: 697503159

Adams County, CO

NENE Section 18 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN FRONT RANGE #2

Location ID: 336057



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates final reclamation has been performed. Well location is reflective of reference area vegetative levels. Sand dropseed is the dominant perennial grass species throughout the well location and reference areas.



Inspection Photos

Location Name: GREAT WESTERN FRONT RANGE #2

Location ID: 336057



**Photo 2.** Photo taken from the well location, facing Northwest towards the former access road. Well location access road is reflective of reference area vegetative levels.



Inspection Photos

Location Name: GREAT WESTERN FRONT RANGE #2

Location ID: 336057



**Photo 3.** Reference photo taken from the well location, facing East. See comments under Photo 1.





**Photo 4.** Photo taken from the associated offsite tank battery, facing North. Photo illustrates the tank battery is still in use for another nearby well with a different Operator.