

Inspection Photos

API: 073-06774

Operator: KODA EXPLORATION LLC

Inspection Date: 8/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 1. Facing north toward the location which is fenced. The location sign is installed by the gate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 2. Facing north toward the location. Interim reclamation has not been performed. Unused areas of the location need to be reclaimed.
Arrow points to the TA well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 3. Facing west at the location. Interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 4. The pit has been backfilled and reclaimed. This is the only area of the location which was reclaimed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 5. Facing southeast at the location. Unused areas of the location are not stabilized and undesirable weeds are establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 6. Facing west at the north side of the location. The topsoil pile has not been replaced back to the original position and contour. The topsoil pile is not maintained or stabilized and there are undesirable weeds growing on the segregated soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 7. Facing south on the pad surface which has not been recontoured. There are signs of wind erosion on the surface.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021

Inspection Photos



Photo 8. There is unused supplies stored on location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06774 | Date: 8/23/2021