

Inspection Photos

API: 073-06776

Operator: KODA EXPLORATION LLC

Inspection Date: 8/23/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021

Inspection Photos



Photo 1. Facing southwest toward the location which is fenced. The location sign is installed by the gate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021

Inspection Photos



Photo 2. Facing southwest toward the location. Interim reclamation has not been performed. All unused areas of the location need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021

Inspection Photos



Photo 3. The pit fencing material is stored at the location and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021

Inspection Photos



Photo 4. Facing northwest at the location. Interim reclamation has not been performed. All unused areas of the location need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021

Inspection Photos



Photo 5. The pit has not been backfilled and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 8/23/2021