

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 1: Pumpjack Sign;WRONG NAME



Photo 2: Tank Battery Sign; UNLEGIBLE

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 3: Stained soil



Photo 4: Stained soil, storage of equipment

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 5: Unused equipment



Photo 6: unused riser, weeds

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 7: Weeds



Photo 8: Unused equipment, weeds

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 9: Weeds, inadequate earth berm



Photo 10: Weeds, inadequate earth berm

Inspection Photos
Location Name: Tigges 3-31B
Location ID: 327053



Photo 11: Weeds, inadequate earth berm, no labeling