

Interim Reclamation and Stormwater Inspection

August 17, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 434399

Inspection Document #: 697503163

Adams County, CO

NENE Section 18 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Willow Bend LD Pad /18-36HN-2

Location ID: 434399



Photo 1. Google Earth aerial imagery taken 5/26/2021. Photo illustrates Operator performed interim reclamation activities in response to a previous corrective action.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503163

Inspection Photos

Location Name: Willow Bend LD Pad /18-36HN-2

Location ID: 434399



Photo 2. Photo taken from the eastern location, facing West. Photo illustrates unused equipment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503163

Inspection Photos

Location Name: Willow Bend LD Pad /18-36HN-2

Location ID: 434399



Photo 3. Photo taken from the eastern location, facing South. Photo illustrates an unmanaged List B Colorado noxious weed, Scotch thistle. Photo illustrates Operator has failed to properly manage the noxious weed to prevent the weed from setting seed and has failed to manage other undesirable plant species.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503163

Inspection Photos

Location Name: Willow Bend LD Pad /18-36HN-2

Location ID: 434399



Photo 4. Photo taken from the southern location, facing West. Photo illustrates unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503163

Inspection Photos

Location Name: Willow Bend LD Pad /18-36HN-2

Location ID: 434399



Photo 5. Photo taken from the southwestern location, facing West. Photo illustrates an unmanaged List B Colorado noxious weed, Musk thistle. Photo illustrates Operator has failed to properly manage the noxious weed to prevent the weed from setting seed and has failed to manage other undesirable plant species.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503163

Inspection Photos
Location Name: Willow Bend LD Pad /18-36HN-2
Location ID: 434399



Photo 6. Photo taken from the southwestern location, facing South. Photo illustrates unmanaged List B Colorado noxious weeds, Scotch and Musk thistle, throughout the interim reclamation areas. Photo illustrates Operator has failed to properly manage the noxious weed to prevent the weed from setting seed and has failed to manage other undesirable plant species.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503163