

# Final Reclamation Inspection

August 17, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320352

Inspection Document #: 697503165

Adams County, CO

NESE Section 7 T1S R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WIERMAN #43-7 (1)  
Location ID: 320352



**Photo 1.** Aerial imagery from 2019 illustrates the well location and tank battery (red circle) and the associated access road.

Inspection Photos  
Location Name: WIERMAN #43-7 (1)  
Location ID: 320352



**Photo 2.** Photo taken from the associated tank battery, facing West. Photo illustrates all equipment has been removed and final reclamation has been performed. Final reclamation will remain in-process since the well location and access road do not yet meet Rule 1004 standards.



Inspection Photos  
Location Name: WIERMAN #43-7 (1)  
Location ID: 320352



**Photo 3.** Photo taken from the well location, facing North. See comments under Photo 2.



Inspection Photos  
Location Name: WIERMAN #43-7 (1)  
Location ID: 320352



**Photo 4.** Photo taken from the northern portion of the access road, facing South. Photo illustrates drill rows and desirable establishment. See comments under Photo 2.

Inspection Photos  
Location Name: WIERMAN #43-7 (1)  
Location ID: 320352



**Photo 5.** Photo taken from the eastern portion of the access road, facing East. Photo illustrates undesirable weeds, Kochia and Russian thistle, which will need to be managed in the future. It appears weed management in the form of mowing was observed.

