

# Inspection Photos

API: 073-06743

Operator: K3 OIL & GAS OPERATING COMPANY

Inspection Date: 8/23/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021

## Inspection Photos



**Photo 1.** Facing at the access road off the county road. The fence has not been reinstalled to prior position shown by red line. There is mostly undesirable weeds along the access road.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021



## Inspection Photos



**Photo 2.** Center of the location facing east. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021



## Inspection Photos



**Photo 3.** Center of the location facing north. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021



## Inspection Photos



**Photo 4.** Center of the location facing west. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021



## Inspection Photos



**Photo 5.** Center of the location facing south. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021



## Inspection Photos



**Photo 6.** View of ground cover shows undesirable vegetation growth; Kochia, Russian thistle. Desirable vegetation has not established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06743 | Date: 8/23/2021