

Inspection Photos
Location Name: RMPCO Kissler #1
Location ID: 319247



Production facility



Clean out plate and stained soil

Inspection Photos
Location Name: RMPCO Kissler #1
Location ID: 319247



Separator and meter run



Battery sign

Inspection Photos
Location Name: RMPCO Kissler #1
Location ID: 319247



Colorado Oil & Gas Conservation Commission
40.30169, -104.78476, 1432.0m, 291°
08/26/2021 09:42:51

Wellhead



Colorado Oil & Gas Conservation Commission
40.30174, -104.78456, 1432.0m, 12°
08/26/2021 09:43:45

Load valve drip bucket and stained soil