

Inspection Photos
Location Name: Horth 41-15 #2
Location ID: 320112



Photo #1 Tanks.



Photo #2 ECD, Separator & Meter.

Inspection Photos
Location Name: Horth 41-15 #2
Location ID: 320112



Photo #3 Well Head.



Photo #4 Stained soil next to produced water tank.

Inspection Photos
Location Name: Horth 41-15 #2
Location ID: 320112



Photo #5 Stained soil next to produced water tank.



Photo #6 Stained soil next to produced water tank.