

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 1 – Pumping Unit**



**Photo 2 – Wellhead – Stained Soil**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 3 – Tank Battery**



**Photo 4 – Tank Battery Sign – Contact Number is peeling, replace in near future**





**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 5 – NFPA Label missing**



**Photo 6 – Stained Soil**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 7 – Stained Soil at NE Loadline**



**Photo 8 – Stained Soil at Drain Valves**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 9 – Oil on Pit**



**Photo 10 – Oil on Pit**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 331730**



**Photo 11 – Unused Gas Meter House and Heater Treater and Weeds**