

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Colorado Oil & Gas Conservation Commission
40.62583, -104.85787, 1567.1m, 130°
Aug 26, 2021 12:37:09 PM

Photo 1: Tank Battery Sign



Colorado Oil & Gas Conservation Commission
40.62586, -104.85798, 1568.0m, 233°
Aug 26, 2021 12:36:53 PM

Photo 2: Bird protector installed

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 3: NFPA placard installed



Photo 4: NFPA placard installed

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 5: Capacity installed; NO CONTENTS displayed



Photo 6: Capacity installed; NO CONTENTS displayed

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 7: Capacity installed; NO CONTENTS displayed



Photo 8: Capacity installed; NO CONTENTS displayed

Inspection Photos
Location Name: Irish Pad N/A
Location ID: 450827



Photo 9: Capacity installed; NO CONTENTS displayed



Photo 10: Capacity installed; NO CONTENTS displayed