



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #1 Sign near wellhead on cyclone fence surrounding wellhead.



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #2 Sign on wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #3 segment of flowline from wellhead to tank battery, note: weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #4. 1 Aboveground tank located inside dirt berm. Poly liner observable. Tank is fenced with cyclone fence panels.



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #5 close up of Photo #4



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #6 Water inside tank battery.



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #7 cemented pipe coming out of ground on Northside of location. What is the purpose of this pipe?



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #8 segment of pipe seen on the northern edge of pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #9 Photo taken looking mostly south. The shed on left is well 107-06175. The Ephphatha well can be seen to right of photo, note: rod coming out of wellhead. Both wells were fenced with cyclone fence panels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel

Photo #10 Water well shed. The water well is identified in the COGCC database as former oil well, api 05-107-06175. The shed was fenced with 6' cyclone fence panels.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

107-06175

Inspection Date: 8/11/2021

All Photos taken by Kris Neidel



Photo #11 Marked Deadman



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources