

Inspection Photos

8/23/2021

Operator: NONSUCH NATURAL GAS INC

#10163

Location ID: 324169

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 1: Photo taken from the interim areas, on the west end of the Location. Unable to find evidence that additional reclamation work was performed; control measures to stabilize the seeded soils not implemented. Photo also shows control measures to protect/stabilize the cut/fill slopes of the Location, and to prevent offsite sediment transport remains missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 2: Photo taken from the interim areas, on the north and east end of the Location. Unable to find evidence that additional reclamation work was performed; control measures to stabilize the seeded soils not implemented. Photo also shows control measures to protect/stabilize the cut/fill slopes of the Location, and to prevent offsite sediment transport remains missing or insufficient.

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 3: Photo provides example of noxious weeds on the Location that have matured with viable seed heads.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 324169



Photo 4: Photo shows erosion degradation along access road; BMPs to stabilize, manage runoff, and minimize erosion are missing or insufficient at the access road; erosion degradation and offsite sediment transport observed on road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC #10163

Location ID: 324169



Photo 5: Photo shows erosion degradation, and offsite sediment transport along access road; BMPs to stabilize, manage runoff, and minimize erosion are missing or insufficient at the access road; erosion degradation and offsite sediment transport observed on road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: NONSUCH NATURAL GAS INC #10163
Location ID: 324169



Photo 6: Photos show hydrocarbon accumulation within the pit on the Location.

