

Inspection Photos

8/23/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 452807

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 1: Photos taken from the southeast end of the Location. Photos provide overview of the Location. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 2: Photos taken from the slopes on the east and west end of the Location. Photo shows control measures to protect and stabilize the slopes of the Location remain missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 452807



Photo 3: Photo taken from the access road. Photo shows additional control measures to stabilize and protect slopes along the access road have been installed.