

Inspection Photos

8/23/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335647

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 1: Photo taken from the southwest end of the Location, facing north/northeast. Photos show interim reclamation of areas not needed for production has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 2: Photo left taken from the southwest end of the Location, facing east. Photo right taken from the south end of the Location, facing east. Photos show interim reclamation of areas not needed for production, including a second access road, has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 3: Photo taken south end of the Location. Photo shows BMPs to protect and stabilize slopes of the Location, and to allow for sediment laden-free stormwater discharge, remains missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 4: Photos show examples of the cut/fill slopes on the Location, where BMPs to protect and stabilize the slopes are missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335647



Photo 5: Photos show examples of the cut/fill slopes on the Location, where BMPs to protect and stabilize the slopes are missing or insufficient