

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 1 – Pumping Unit



Photo 2 – Wellhead – Stained Soil/Leaking Valve

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 3 – Wellhead Sign



Photo 4 – Heater Treater – Weeds

Inspection Photos
Location Name: Bounty #1
Location ID: 322914



Photo 5 – Tank Battery



Photo 6 – Produced Water Tank – Weeds