

**Inspection Photos**  
**Operator: El Paso Natural Gas**  
**API: 067-05538**  
**Date: 8/26/2021**



Photo 1. View of the wellhead facing northward. Corrective actions identified during 2016 inspection are not addressed.



Photo 2. View of cement debris that remains within the project area.



Photo 3. View of the reference area, comprised of cropfield, that is not planted at this time.