

Inspection Photos

API: 071-06976

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/27/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06976 | Date: 8/27/2021

Inspection Photos



Photo 1. Facing north towards the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06976 | Date: 8/27/2021

Inspection Photos



Photo 2. Facing toward the pit. There are noxious weeds (Diffuse knapweed) shown at red arrow. Some of the noxious weeds are beginning to disperse seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06976 | Date: 8/27/2021

Inspection Photos



Photo 3. Facing south on the pit berm. There are noxious weeds (Diffuse knapweed) shown at red arrow and on the backside. Some of the noxious weeds are beginning to disperse seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06976 | Date: 8/27/2021