

# Inspection Photos

API: 071-06903

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/27/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06903 | Date: 8/27/2021

## Inspection Photos



**Photo 1.** Facing east along the main road traveling to the well site. There is erosion along the road side. This area needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 8/27/2021



## Inspection Photos



**Photo 2.** Facing southeast along the main road traveling to the well site. There is erosion along the road side. This area needs to be repaired and stabilized. Red arrow points to the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 8/27/2021



## Inspection Photos



**Photo 3.** Facing south along the access road. There is erosion along the road that needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 8/27/2021



## Inspection Photos



**Photo 4.** Facing east toward the well site. There was Diffuse knapweed observed at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06903 | Date: 8/27/2021