

**Inspection Photos**  
**Location Name: Pergamos 3-7-60 CTB**  
**Location ID: 429096**



**Photo 1 – Pumping Units**



**Photo 2 – Unused Rods**

**Inspection Photos**  
**Location Name: Pergamos 3-7-60 CTB**  
**Location ID: 429096**



**Photo 3 – Weeds in Interim Reclamation Area**

**Photo 4 – Weeds in Interim Reclamation Area**

**Inspection Photos**  
**Location Name: Pergamos 3-7-60 CTB**  
**Location ID: 429096**



**Photo 5 – Weeds in Interim Reclamation Area**

**Photo 6 – Weeds in Interim Reclamation Area**

**Inspection Photos**  
**Location Name: Pergamos 3-7-60 CTB**  
**Location ID: 429096**



**Photo 7 – ECDs**



**Photo 8 – Tank Battery**

Inspection Photos  
Location Name: Pergamos 3-7-60 CTB  
Location ID: 429096



**Photo 9 – Heater Treaters**

**Photo 10 – Tank Battery**