

Inspection Photos
Location Name: Kummer PC LE23-99HZ
Location ID: 421018



Photo 1 – Pumping Unit



Photo 2 – Wellhead



Inspection Photos
Location Name: Kummer PC LE23-99HZ
Location ID: 421018



Photo 3 – Heater Treater and ECDs



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Kummer PC LE23-99HZ
Location ID: 421018



Photo 5 – Tank Battery