

# Inspection Photos

8/26/2021

Operator: WINDSOR ENERGY GROUP LLC

#10081

Location ID: 315696

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 315696



**Photo 1:** Photo show reclamation of access road has not been conducted. Photo right also provides example of noxious weeds (Halogeton) observed along access road and Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: WINDSOR ENERGY GROUP LLC #10081  
Location ID: 315696



**Photo 2:** Photos provide example of various trash/debris remaining along access road and Location.





Inspection Photos  
Operator Name: WINDSOR ENERGY GROUP LLC #10081  
Location ID: 315696



**Photo 3:** Photos provide example of various trash/debris remaining along access road and Location.



Inspection Photos  
Operator Name: WINDSOR ENERGY GROUP LLC #10081  
Location ID: 315696



**Photo 4:** Photos taken from the access road. Photos provide example of stormwater erosion observed on the Location.



## Inspection Photos

Operator Name: WINDSOR ENERGY GROUP LLC #10081

Location ID: 315696



**Photo 5:** Photos taken from the well site, facing south. Photos show Location has not been reclaimed in accordance with 1004 rules.