

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/30/2021

Submitted Date:

08/31/2021

Document Number:

701101886

**FIELD INSPECTION FORM**
 Loc ID 334494 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274779	WELL	PR	03/01/2020	GW	077-08839	GUNDERSON FEDERAL 12-7	PR
276733	WELL	PR	05/30/2012	GW	077-08858	GUNDERSON 12-6	PR
276873	WELL	PR	02/01/2015	GW	077-08861	GUNDERSON 12-11	PR
276917	WELL	PR	01/01/2020	GW	077-08862	GUNDERSON 12-15	PR
277220	WELL	PR	08/01/2011	GW	077-08869	GUNDERSON FEDERAL 12-16	PR
277221	WELL	PR	04/01/2021	GW	077-08868	Gunderson Federal 12-9	PR
277222	WELL	PR	08/18/2010	GW	077-08867	Gunderson Federal 12-8	PR

**General Comment:****COGCC Routine Inspection Report Summary**

During this inspection the following compliance issues were observed

Production horizontal separator includes two glycol storage tanks, approximately 42" x 32" x 170" / 9702 cu in per 1 bbl= 23.5 BBL per tank and vertical separator with one storage tank, approximately 59" x 48" x 118" / 9702 cu in per 1 bbl=34.4 BBL

23.5 bbl + 23.5 bbl + 34.4 bbl = 81.4 bbl

Storage vessel contains no labeling to specify capacity or chemical hazard information.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

## Location

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production horizontal separator includes two glycol storage tanks, approximately 42" x 32" x 170" / 9702 cu in per 1 bbl= 23.5 BBL per tank and vertical separator with one storage tank, approximately 59" x 48" x 118" / 9702 cu in per 1 bbl=34.4 BBL 23.5 bbl + 34.4 bbl = 81.4 bbl Storage vessel contains no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/01/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Faded Danger and warning stickers on separators.		
Corrective Action:		Date:	

## Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	2 tank batteries		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:	Triple unit vertical separator with one storage tank, approximately 59" x 48" x 118" / 9702 cu in per 1 bbl=34.4 BBL		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:	Quad unit horizontal separator includes two glycol storage tanks, approximately 42" x 32" x 170" / 9702 cu in per 1 bbl= 23.5 BBL per tank Total of 47 bbl.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	Battery on backend of location.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallons
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	Battery at entrance				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallons
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Battery on backend of location.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:	Battery at entrance				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	274779	Type:	WELL	API Number:	077-08839	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	276733	Type:	WELL	API Number:	077-08858	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	276873	Type:	WELL	API Number:	077-08861	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	276917	Type:	WELL	API Number:	077-08862	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	277220	Type:	WELL	API Number:	077-08869	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	277221	Type:	WELL	API Number:	077-08868	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	277222	Type:	WELL	API Number:	077-08867	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Gravel						
Compaction						
		Gravel				
Ditches						
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101892	Inspection 701101886 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5519835</a>